







Parts are NOT to scale

Model 18/28 Base Diagram

Oct 2003



 Tubing
 Spin Weld
 Washer
 Hose Clamp (pinch)
 Hose Clamp, Adjustable Metal (worm gear)

<p>Pump Assembly 110v 15/15C/18 (includes liquid tight tubing & connectors) pn. 6282PUMPASY1</p>	<p>Pump Kit M/C 110v 15/15C/18 (includes liquid tight tubing, connectors, and plumbing to sink) pn. 6142PUMPKITMC</p>	<p>Heater Box Assembly M/C 110v (includes heater, probe, box, & fittings) pn. 6280HTRBOX</p>
---	--	---